


## Accessories and Spare Parts



Part No	Description	Part No	Description	Part No	Description
16 40 05	Ear and neck protection in leather.	75 00 10	Speedglas welding filter 100S-10, single shade 10.	75 20 90	100 welding helmet Wild n' Pink, without welding filter, without headband.
16 75 20	Sweatband, towelling purple, pkg of 2.	75 00 11	Speedglas welding filter 100S-11, single shade 11.	75 21 90	100 welding helmet Steel Eyes, without welding filter, without headband.
16 76 00	Sweatband, towelling purple, pkg of 20.	75 00 20	Speedglas welding filter 100V, variable shade 8-12.	75 22 90	100 welding helmet Xterminator, without welding filter, without headband.
16 80 00	Sweatband, leather.	75 05 11	Speedglas 100 passive kit: 110x90 mm passive welding filter shade 11, inner cover plate, outer protection plate and filter frame (not shown).	75 23 90	100 welding helmet Boneyard, without welding filter, without headband.
16 80 10	Sweatband, fleecy cotton.	75 11 00	100 welding helmet black, without welding filter with headband.	75 24 90	100 welding helmet Razor Dragon, without welding filter, without headband.
16 90 01	Neck protection, black/grey.	75 11 90	100 welding helmet black, without welding filter, without headband.	75 25 90	100 welding helmet Ice Hot, without welding filter, without headband.
16 91 00	Hood black/grey	75 12 90	100 welding helmet Blaze, without welding filter, without headband.	75 26 90	100 welding helmet Raging Skull, without welding filter, without headband.
17 10 20	Magnifying lens 1.0.	75 16 90	100 welding helmet Trojan Warrior, without welding filter, without headband.	77 20 00	Front frame, silver.
17 10 21	Magnifying lens 1.5.	75 17 90	100 welding helmet Aces High, without welding filter, without headband.	77 20 01	Front frame, black.
17 10 22	Magnifying lens 2.0.	75 18 90	100 welding helmet Steel Rose, without welding filter, without headband.	77 60 00	Outer protection plate, standard, pkg of 10.
17 10 23	Magnifying lens 2.5.	75 19 90	100 welding helmet Skull Jewels, without welding filter, without headband.	77 70 00	Outer protection plate, scratch resistant, pkg of 10.
17 10 24	Magnifying lens 3.0.			77 70 70	Outer protection plate, heat resistant, pkg of 10.
19 71 34	Speedyloop with assembly parts.			G3001NUV-VI	Peltor safety helmet G3001
42 20 00	Battery, pkg of 2.				
42 80 00	Inner cover plate, pkg of 5. Plate marking 42 02 00.				
42 80 20	Inner cover plate, +1 shade, pkg of 5.				
42 80 40	Inner cover plate, +2 shade, pkg of 5.				
70 50 15	New headband (Sept 2012) with assembly parts.				
70 60 00	Assembly parts for headband.				
73 10 00	Battery cover.				